

TRANSMITTAL LETTER

Weston Solutions, Inc.
14160 N. Dallas Parkway, Suite 850
Dallas, Texas 75254
Phone: (469) 374-7700

Lee Dee Ortiz
~~Thomas Walzer~~



Nancy Jones
Yes, Approved

9 November 2009

To: U.S. Environmental Protection Agency
1445 Ross Avenue
Dallas, TX 75202

Project: Exxon Mobil Baytown
Contract No. EP-W-06-042
TDD: TO-0001-09-08-01
Work Order Number: 20406.012.001.0458.01
Report Date: 02 September 2009

Attn: ☒ Ginny Hope (6SF-VC)
☐ Lamonica Collins (6SF-RO)

WESTON TRANSMITS THE FOLLOWING:

<input checked="" type="checkbox"/> Report/Work Plan	<input type="checkbox"/> Drawings	<input type="checkbox"/> Calculations
<input type="checkbox"/> Letter	<input type="checkbox"/> Meeting Minutes	<input type="checkbox"/> Product Information
<input type="checkbox"/> Memorandum	<input type="checkbox"/> Contract Documents	<input type="checkbox"/> Other

ITEM NO.	NO. COPIES	DESCRIPTION	ACTION
1	2	Emergency Response Report for Exxon Mobil Baytown 5000 Bayway Drive Baytown, Harris County, Texas	D

A - For Your Information
B - For Your Approval
C - For Your Review and Comment

D - For Your Files
E - Reply Requested
F - Other

REMARKS: If you have any questions and/or comments, please contact Thomas Walzer in our Houston office at 713-985-6600 at your earliest convenience.

COPIES TO: 1 DTX
2 EPA
Non-Petroleum – Ginny Hope (6SF-VC)
Petroleum Related – Lamonica Collins (6SF-RO)

SIGNED: *Thomas Walzer*
Thomas Walzer
Project Team Leader

9116697



TABLE OF CONTENTS

- ✓ EMERGENCY RESPONSE REPORT
- ✓ PROJECT SUMMARY
- ✓ TABLE OF CONTENTS
- ✓ 1. PROJECT IDENTIFICATION
- ✓ 2. INTRODUCTION
- ✓ 3. BACKGROUND
- ✓ 4. ACTIONS TAKEN
- ✓ 5. LIST OF ATTACHMENTS

12.47kV distribution lines were found severed (four cables total). At the time of the writing of this report, Exxon Mobil representatives continue to investigate the failures and original cause of the pipe rupture and fire.

This final report was prepared as part of the requirements of the TDD and serves as documentation of work completed to date.

5.0 LIST OF ATTACHMENTS

- ✓A. Site Location Map
- ✓B. Site Area Map
- ✓C. Fire Location Map
- ✓D. Exxon Mobil Air Monitoring Results
- ✓E. AEERD Reports
- ✓F. Digital Photographs
- ✓G. Copy of NRC Report Nos. 914039; 914040; and 914041
- ✓H. Copy of POLREPs
- ✓I. Copy of START-3 Site Logbook
- ✓J. Copy of TDD No. TO-0001-09-08-01 and Amendment A